

- SAT not found (updating the SMART drives description database):
 - https://www.smartmontools.org/wiki/FAQ#MyATASATA_drive_is_not_in_the_smartctl_smartd_database
- i8042: No controller found
- *ERROR* No UMS support in radeon module - adding the parameter radeon.dpm=0 to the kernel parameters as suggested at wiki.archlinux.org/index.php/ATI

From:

<https://dulib.re/wiki/> - **Le Goût du Libre**

Permanent link:

<https://dulib.re/wiki/doku.php/hpproliantmicroserver>

Last update: **2017/01/02 08:31**

